



03N21W11H03S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W11J01S




SCREEN: 58-222 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W11J02S




SCREEN: 260-700 ft bgs | CURRENT USE: Municipal | STATUS: Active

03N21W11P01S




SCREEN: Unknown ft bgs | CURRENT USE: Industrial | STATUS: Destroyed

03N21W12B02S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Abandoned

03N21W12B04S




SCREEN: 120-360 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12D03S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Can't Locate

03N21W12E02S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Can't_Locate_Indeterminable

03N21W12E03S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Destroyed

03N21W12E04S




SCREEN: 120-284 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12E08S




SCREEN: 120-285 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12F02S




SCREEN: 66-133 ft bgs | CURRENT USE: Agricultural | STATUS: Non-Compliant_Abandoned

03N21W12F03S




SCREEN: 120-284 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12F06S




SCREEN: 120-395 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12F07S




SCREEN: 120-400 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12H01S




SCREEN: 74-150 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W15C02S




SCREEN: 176-322 ft bgs | CURRENT USE: Municipal | STATUS: Active

03N21W15C03S




SCREEN: 112-252 ft bgs | CURRENT USE: Agricultural | STATUS: Can't Locate

03N21W15C04S




SCREEN: 112-253 ft bgs | CURRENT USE: Municipal | STATUS: Active

03N21W15C05S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N21W15C06S




SCREEN: 452-653 ft bgs | CURRENT USE: Municipal | STATUS: Active

03N21W15G01S




SCREEN: 660-680 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

03N21W15G02S




SCREEN: 520-540 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

03N21W15G03S




SCREEN: 370-390 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

03N21W15G04S




SCREEN: 260-280 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

03N21W15G05S




SCREEN: 60-80 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W03K01S




SCREEN: 40-70 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W19P01S




SCREEN: 202-295 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W19P03S




SCREEN: 415-630 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W19R01S




SCREEN: 220-401 ft bgs | CURRENT USE: Agricultural | STATUS: Unknown

04N18W20K01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N18W20M01S




SCREEN: 220-420 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N18W20M02S




SCREEN: 160-369 ft bgs | CURRENT USE: Domestic | STATUS: Destroyed

04N18W20M03S




SCREEN: 160-450 ft bgs | CURRENT USE: Municipal | STATUS: Active

04N18W20M04S




SCREEN: 160-470 ft bgs | CURRENT USE: Municipal | STATUS: Active

04N18W20N01S




SCREEN: 220-441 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N18W20P02S




SCREEN: 137-177 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W20P04S




SCREEN: 100-140 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W20R01S




SCREEN: 190-319 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W27B01S




SCREEN: 156-280 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N18W27B02S




SCREEN: 140-255 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W27G03S




SCREEN: 40-120 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W27H01S



SCREEN: 40-120 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W28C02S



SCREEN: 390-750 ft bgs | CURRENT USE: Agricultural | STATUS: Active


Groundwater Elevation, ft amsl



Groundwater Elevation, ft amsl




04N18W29M02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W29P01S




SCREEN: Unknown-232 ft bgs | CURRENT USE: Agricultural | STATUS: Can't_Locate_Indeterminable

04N18W29P03S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Destroyed

04N18W29P04S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Non-Compliant_Abandoned

04N18W29P05S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Non-Compliant_Abandoned

04N18W30A01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N18W30G01S




SCREEN: 282-392 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W30G02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W30G04S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

04N18W30J05S




SCREEN: 52-207 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W30K01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

04N18W30M02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N18W31C01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

04N18W31D03S




SCREEN: 590-610 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D04S




SCREEN: 310-330 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D05S




SCREEN: 220-240 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D06S




SCREEN: 140-160 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D07S




SCREEN: 50-70 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N19W25A02S




SCREEN: 267-460 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25B01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N19W25C01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25C02S




SCREEN: 265-504 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25J05S




SCREEN: 180-380 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25K02S




SCREEN: 120-290 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N19W25K04S




SCREEN: 220-370 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25M01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25M02S




SCREEN: 526-626 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W26J03S




SCREEN: 400-650 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W26P01S




SCREEN: 212-268 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W26P02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W26Q01S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Destroyed

04N19W27Q01S




SCREEN: 272-335 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W27R01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W28Q01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned

04N19W29L01S




SCREEN: Unknown-280 ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned

04N19W29L03S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Can't Locate

04N19W29Q01S




SCREEN: 80-160 ft bgs | CURRENT USE: Agricultural | STATUS: Can't Locate

04N19W30D01S




SCREEN: 60-380 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W30J02S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't Locate

04N19W30R01S




SCREEN: 173-300 ft bgs | CURRENT USE: Domestic | STATUS: Destroyed

04N19W31D02S




SCREEN: 141-184 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N19W31E01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W31F01S




SCREEN: 60-100 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W31N03S




SCREEN: 105-169 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W31Q01S




SCREEN: 100-250 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W31R01S




SCREEN: 60-137 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W31R02S




SCREEN: 62-120 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N19W32A01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Can't_Locate_Indeterminable

04N19W32B01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N19W32B02S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Destroyed

04N19W32B03S




SCREEN: 60-173 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W32F02S




SCREEN: 81-245 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W32G01S




SCREEN: 136-409 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W32J03S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Can't Locate

04N19W32M02S




SCREEN: 180-300 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W32P01S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Destroyed

04N19W32R01S




SCREEN: 30-90 ft bgs | CURRENT USE: Municipal | STATUS: Destroyed

04N19W32R02S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Destroyed

04N19W33B01S




SCREEN: 206-306 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W33C01S




SCREEN: 165-400 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W33D01S




SCREEN: 25-95 ft bgs | CURRENT USE: Unknown | STATUS: Can't Locate

04N19W33D03S




SCREEN: 140-506 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W33D04S




SCREEN: 140-486 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W33H01S




SCREEN: 237-362 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W33J01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W33M02S




SCREEN: Unknown ft bgs | CURRENT USE: Municipal | STATUS: Active

04N19W33M03S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W33M05S




SCREEN: 37-107 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34B01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34D01S




SCREEN: 160-304 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34D02S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Destroyed

04N19W34J01S




SCREEN: 72-120 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34J02S




SCREEN: 35-103 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N19W34J04S




SCREEN: 60-160 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34K01S




SCREEN: 5-120 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34L01S




SCREEN: 90-430 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34M02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W35C01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W35G01S




SCREEN: 24-79 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N19W35H01S




SCREEN: 18-48 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N19W35H02S




SCREEN: 18-48 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N19W35K02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W35L02S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W36D01S




SCREEN: 18-73 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N20W12G02S




SCREEN: 80-100 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N20W13N01S




SCREEN: 203-403 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W22N01S




SCREEN: 200-400 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W22N03S




SCREEN: 450-1580 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W23J01S




SCREEN: 196-240 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N20W23N01S




SCREEN: 219-388 ft bgs | CURRENT USE: Domestic | STATUS: Abandoned

04N20W23N02S




SCREEN: 220-390 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W23Q02S




SCREEN: 327-567 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W24C02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned_HOLD

04N20W24G01S




SCREEN: 100-260 ft bgs | CURRENT USE: Municipal | STATUS: Active

04N20W24Q03S




SCREEN: 120-300 ft bgs | CURRENT USE: Monitoring | STATUS: Abandoned_HOLD

04N20W24Q04S




SCREEN: 90-300 ft bgs | CURRENT USE: Municipal | STATUS: Active

04N20W25B03S




SCREEN: 100-260 ft bgs | CURRENT USE: Municipal | STATUS: Active

04N20W25D01S




SCREEN: 67-187 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W25N02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

04N20W26A02S




SCREEN: 40-254 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W26B02S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Abandoned

04N20W26C02S




SCREEN: 155-255 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N20W26D01S




SCREEN: 180-500 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W26H01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Destroyed


04N20W26L01S



04N20W27N01S




04N20W31H02S




SCREEN: 370-610 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W31H04S




SCREEN: 280-640 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W31L01S




SCREEN: 633-1100 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W33C03S




SCREEN: 470-700 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W36D04S




SCREEN: 34-68 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N20W36MW104




SCREEN: 10-40 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N20W36N02S




SCREEN: 62-84 ft bgs | CURRENT USE: Agricultural | STATUS: Non-Compliant

05N18W15P01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Abandoned_HOLD

05N18W33G02S




SCREEN: 24-193 ft bgs | CURRENT USE: Domestic | STATUS: Abandoned_HOLD

05N18W33MW8



SCREEN: 30-110 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

05N18W33MW113




SCREEN: 30-90 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

Appendix B

Groundwater Level
Hydrographs
High-Frequency Data from
Recording Pressure
Transducers


03N20W03D03S

Last of RP ELEVATION: 342.01 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD




03N20W03H01S

Last of RP ELEVATION: 357.66 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD




03N20W05D03S




03N20W07HRP9


Last of RP ELEVATION: 294.89 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD



03N20W08VCWPD8




03N21W02R02S




03N21W11B01S

Last of RP ELEVATION: 336.24 ft amsl | BASIN: Santa Paula | MONITORING NETWORK: None




03N21W11F04S




03N21W11H03S


Last of RP ELEVATION: 308.39 ft amsl | BASIN: Santa Paula | MONITORING NETWORK: UWCD




03N21W12B04S




03N21W12E04S




03N21W12E08S




03N21W12F02S



03N21W12F03S




03N21W12F06S




03N21W12F07S


Last of RP ELEVATION: 282.37 ft amsl | BASIN: Fillmore | MONITORING NETWORK: None



03N21W12H01S




03N21W15C04S




03N21W15G03S_SP1-390

Last of RP ELEVATION: 244.94 ft amsl | BASIN: Santa Paula | MONITORING NETWORK: UWCD




03N21W15G05S_SP1-80

Last of RP ELEVATION: 244.94 ft amsl | BASIN: Santa Paula | MONITORING NETWORK: UWCD




04N18W20M01S




04N18W20P02S_PSG-190

Last of RP ELEVATION: 667.02 ft amsl | BASIN: Piru | MONITORING NETWORK: UWCD




04N18W20P04S_PSG-140


Last of RP ELEVATION: 667.19 ft amsl | BASIN: Piru | MONITORING NETWORK: UWCD




04N18W29M02S




04N18W31D03S_RP-610




04N18W31D04S_RP-330




04N18W31D07S_RP-70




04N19W25A02S




04N19W32F02S



04N19W34D01S




04N19W36D01S




04N20W23N01S

Last of RP ELEVATION: 559 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD




04N20W24C02S

Last of RP ELEVATION: 497.02 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD




04N20W24Q03S




04N20W25B03S

Last of RP ELEVATION: 439.1 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD




04N20W36MW104



Appendix C


Select Groundwater Level
Trend Analysis
Hydrographs

03N19W06D02S




SCREEN: 216-405 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01C04S




SCREEN: 49-218 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02A01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W03N01S




SCREEN: 120-172 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W05D01S




SCREEN: 215-315 ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned_HOLD

03N20W05D03S




SCREEN: 200-385 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W08A01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W09D01S




SCREEN: 210-310 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W11C01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W01N02S




SCREEN: 200-400 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed


03N21W01P02S



03N21W12B02S




03N21W12B04S




SCREEN: 120-360 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12F07S




SCREEN: 120-400 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N21W12H01S




SCREEN: 74-150 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W19R01S




SCREEN: 220-401 ft bgs | CURRENT USE: Agricultural | STATUS: Unknown

04N18W20M02S




SCREEN: 160-369 ft bgs | CURRENT USE: Domestic | STATUS: Destroyed

04N18W20P02S




SCREEN: 137-177 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W20P04S




SCREEN: 100-140 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W20R01S




SCREEN: 190-319 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W27B02S




SCREEN: 140-255 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W28C02S




SCREEN: 390-750 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W29M02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N18W29P01S




SCREEN: Unknown-232 ft bgs | CURRENT USE: Agricultural | STATUS: Can't_Locate_Indeterminable

04N18W31D03S




SCREEN: 590-610 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D04S




SCREEN: 310-330 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D05S




SCREEN: 220-240 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D06S




SCREEN: 140-160 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N18W31D07S




SCREEN: 50-70 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N19W25C02S




SCREEN: 265-504 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25K04S




SCREEN: 220-370 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W25M01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active


04N19W26P01S



04N19W30D01S




04N19W31Q01S




SCREEN: 100-250 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W31R01S




SCREEN: 60-137 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W32M02S




SCREEN: 180-300 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W33D03S




SCREEN: 140-506 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W33D04S




SCREEN: 140-486 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W34J01S




SCREEN: 72-120 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W34K01S




SCREEN: 5-120 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N19W35G01S




SCREEN: 24-79 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N19W35L02S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

04N19W36D01S




SCREEN: 18-73 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

04N20W23Q02S




SCREEN: 327-567 ft bgs | CURRENT USE: Agricultural | STATUS: Active

04N20W24C02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned_HOLD

04N20W24Q03S




SCREEN: 120-300 ft bgs | CURRENT USE: Monitoring | STATUS: Abandoned_HOLD

04N20W26C02S




SCREEN: 155-255 ft bgs | CURRENT USE: Domestic | STATUS: Active

04N20W26L01S




04N20W33C03S



04N20W36MW104

Last of RP ELEVATION: 413.83 ft amsl | BASIN: Fillmore | MONITORING NETWORK: UWCD

Groundwater Elevation, ft amsl




SCREEN: 10-40 ft bgs | CURRENT USE: Monitoring | STATUS: Unknown

Appendix D


Groundwater Quality Time-Series Graphs

03N19W05D01S




SCREEN: 60-137 ft bgs | CURRENT USE: Agricultural | STATUS: Can't_Locate_Report

03N19W05D01S




SCREEN: 60-137 ft bgs | CURRENT USE: Agricultural | STATUS: Can't_Locate_Report

03N19W06C03S




SCREEN: 100-180 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N19W06C03S




SCREEN: 100-180 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N19W06D01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Non-Compliant_Abandoned

03N19W06D01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Non-Compliant_Abandoned

03N19W06D02S




SCREEN: 216-405 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N19W06D02S




SCREEN: 216-405 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N19W06D03S




SCREEN: 184-400 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N19W06D03S




SCREEN: 184-400 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N19W06D04S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N19W06D04S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N19W07D01S




SCREEN: 160-200 ft bgs | CURRENT USE: Industrial | STATUS: Active

03N19W07D01S




SCREEN: 160-200 ft bgs | CURRENT USE: Industrial | STATUS: Active

03N20W01A03S




SCREEN: 385-545 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01A03S




SCREEN: 385-545 ft bgs | CURRENT USE: Agricultural | STATUS: Active


03N20W01C03S



03N20W01C03S




03N20W01C04S




SCREEN: 49-218 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01C04S




SCREEN: 49-218 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01D03S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01D03S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01E01S



SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W01E01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W01F01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01F01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01F05S




SCREEN: 100-200 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W01F05S




SCREEN: 100-200 ft bgs | CURRENT USE: Domestic | STATUS: Active


03N20W01G01S




03N20W01G01S




03N20W01G02S



03N20W01G02S




03N20W01G03S




SCREEN: 200-280 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01G03S




SCREEN: 200-280 ft bgs | CURRENT USE: Agricultural | STATUS: Active


03N20W01H03S



03N20W01H03S




03N20W01J01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01J01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W01L01S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't_Locate_Indeterminable

03N20W01L01S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't_Locate_Indeterminable

03N20W01L02S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't_Locate_Indeterminable

03N20W01L02S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't_Locate_Indeterminable

03N20W01L04S



03N20W01L04S




03N20W01P01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned

03N20W01P01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Abandoned

03N20W01P02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Can't Locate

03N20W01P02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Can't Locate

03N20W01P04S




SCREEN: 70-110 ft bgs | CURRENT USE: Domestic | STATUS: Abandoned

03N20W01P04S




SCREEN: 70-110 ft bgs | CURRENT USE: Domestic | STATUS: Abandoned

03N20W01P05S




SCREEN: 71-305 ft bgs | CURRENT USE: Domestic | STATUS: Non-Compliant_Abandoned

03N20W01P05S




SCREEN: 71-305 ft bgs | CURRENT USE: Domestic | STATUS: Non-Compliant_Abandoned

03N20W02A01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02A01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02A04S




SCREEN: 80-100 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02A04S




SCREEN: 80-100 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02B01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02B01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02B02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02B02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02B05S




SCREEN: 131-251 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02B05S




SCREEN: 131-251 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02E01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02E01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02E02S




SCREEN: 133-205 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02E02S




SCREEN: 133-205 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02F03S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't Locate

03N20W02F03S




SCREEN: Unknown ft bgs | CURRENT USE: Unknown | STATUS: Can't Locate

03N20W02F04S




SCREEN: 60-108 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02F04S




SCREEN: 60-108 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02F05S




SCREEN: 96-265 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02F05S




SCREEN: 96-265 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02G03S




SCREEN: 120-200 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02G03S




SCREEN: 120-200 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02H01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02H01S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02H05S




SCREEN: 238-310 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02H05S




SCREEN: 238-310 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02L03S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02L03S




SCREEN: Unknown ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02L04S




SCREEN: 82-131 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02L04S




SCREEN: 82-131 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02L06S




SCREEN: 48-80 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02L06S




SCREEN: 48-80 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02M01S




SCREEN: 161-305 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02M01S




SCREEN: 161-305 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02M02S




SCREEN: 122-162 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02M02S




SCREEN: 122-162 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02N01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W02N01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W02R04S




SCREEN: 90-125 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W02R04S




SCREEN: 90-125 ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W02R05S




SCREEN: 93-133 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02R05S




SCREEN: 93-133 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02R06S




SCREEN: 105-255 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02R06S




SCREEN: 105-255 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W02R08S




SCREEN: 60-200 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W02R08S




SCREEN: 60-200 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W03D01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W03D01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W03D02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W03D02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W03D03S




SCREEN: 102-397 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D03S




SCREEN: 102-397 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D04S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W03D04S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Destroyed

03N20W03D05S




SCREEN: 274-436 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D05S




SCREEN: 274-436 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D07S




SCREEN: 224-484 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D07S




SCREEN: 224-484 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D08S




SCREEN: 450-600 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03D08S




SCREEN: 450-600 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03J01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03J01S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03N01S




SCREEN: 120-172 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03N01S




SCREEN: 120-172 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03N02S




SCREEN: 76-330 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W03N02S




SCREEN: 76-330 ft bgs | CURRENT USE: Agricultural | STATUS: Active


03N20W03N03S



03N20W03N03S




03N20W04C01S




SCREEN: 160-332 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04C01S




SCREEN: 160-332 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04E02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04E02S




SCREEN: Unknown ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04N01S




SCREEN: 136-227 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W04N01S




SCREEN: 136-227 ft bgs | CURRENT USE: Domestic | STATUS: Active

03N20W04N03S




SCREEN: 186-266 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04N03S




SCREEN: 186-266 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04N04S



SCREEN: 60-155 ft bgs | CURRENT USE: Agricultural | STATUS: Active

03N20W04N04S



SCREEN: 60-155 ft bgs | CURRENT USE: Agricultural | STATUS: Active